Washington Creek

- Failed Concrete Retaining Wall
- Clogged V-Ditch
- Displaced Concrete liner
- Immediate Action
 - Clear drainage holes in structure
 - Remove Vegetation
 - · Re-establish V Ditch





Washington Creek








December 2023



March 2024



June 2023




March 2024





Washington Creek: Historical





Sonoma Water

Clean. Reliable. Essential. Every Day.

Flood Zone 2A

SONOMA WATER: STREAM MAINTENANCE PROGRAM UPDATE 2023

Chase Takajo 12/14/23











Vegetation Management

- Adobe Creek
- East Washington
 Creek
- Lichau Creek
- Lynch Creek
- Washington Creek



Lower Lichau Creek







Upper Lichau Creek








Upper Lichau Creek







Lichau Creek Blockage Removal



Blockage 1, before, 10/2/23.



Blockage 1, after, 10/3/23.



Blockage 7, before, 10/4/23.



Blockage 7, after, 10/10/23.



Debris and Trash Removal



Security Guard Patrolling Channels (Water Agency Owned)

Weekly As needed Clean ups

9,300 lbs. of Trash Removed



Sediment Removal

- Adobe Creek: Sediment Basins
 - Casa Grande Rd
 - 1,706 CY removed
 - S Mcdowell Rd
 - 1,496 CY removed
- Washington Creek: Sediment Basin
 - Maria Dr
 - 616 CY removed
- Lichau Creek: Localized
 - Main St.
 - 176 CY removed



Adobe Creek at Casa Grande Rd








Washington Creek at Maria Dr







Lichau Creek downtown Penngrove







Lichau Creek








Upcoming Projects

- Cultural Resource Monitoring Plan for SMP
 - BMP implementation
 - On Site Monitors
 - Request for Proposals have gone out
 - Review and interview consultants



Sonoma OneRain System

- OneRain
 - Sonoma.onerain.com
 - Real time rainfall, river-stream and reservoir data





Questions?











